

RMSTATOR
THE POWER IN POWERSPORTS

ESTABLISHED
SINCE 1993



PWVC

PARTS 2016

CONTACT US

Toll Free (Canada & USA): 1-877-838-1399

Local & International: 819-849-7333

Fax: 819-849-6660

For written inquiries, FAQ and more, visit our Online Customer Service Center at support.rmstator.com or contact us by e-mail at support@rmstator.com

Business hours

Eastern Standard Time

Monday to Thursday: 8AM to 5PM

Friday: 8AM to 4PM

Saturday & Sunday: Closed

Headquarters

Canadian Headquarters

541, Main Ouest, Coaticook
(Québec) Canada J1A 1R2

RMSTATOR Return Addresses

Canadian &

International Customers

RMSTATOR

541, Main Ouest, Coaticook

(Quebec) Canada, J1A 1R2

United States Customers

RMSTATOR

395 Caswell Ave

Derby line VT 05830

Order fulfillment

Orders received after 11:30am EST will only be sent out the next business day.

Sales

Any sales inquiries, new corporate accounts and opportunities requests must be sent to

sales@rmstator.com

RMSTATOR clients around the world



Table of contents

01. PRODUCTS	5
CHARGING SYSTEM	5
IGNITION SYSTEM	11
STARTING SYSTEM	15
TOOLS AND MISC. PRODUCTS	19
UNIVERSAL PRODUCTS	21

A woman in a wetsuit and life vest is riding a blue PWC (Personal Water Craft) on the water. The image is overlaid with a semi-transparent blue filter. The text 'PWC PARTS' is prominently displayed in white, bold, sans-serif font across the center of the image.

PWC PARTS

CHARGING SYSTEM

For OEM cross reference, product specifications and more information please visit: www.rmstator.com

Enhanced Technology

This icon indicates that the product is an advanced technology that either lowers operating temperatures to provide extended longevity or shuts down the system before burning to protect critical electrical components. The Enhanced Technology icon identifies products that offer better performance than the OEM component.

Gaskets

You wouldn't use the same oil filter twice, would you? Then why would you even consider reusing an old gasket? Save yourself the headache and hassle of dealing with a leaking gasket by installing a new gasket every time you open the engine case.

Connectors

Make sure all of your electrical connectors are in proper working order by replacing them along with your new part. Shop connectors at www.rmstator.com/connectors.

Flywheel Pullers

Make sure you have the right tool for the job. Attempting to remove a flywheel without a flywheel puller can cause significant and costly damage to your crankshaft. Be sure to lubricate the necessary areas liberally and use only the appropriate hand tools. Always wear safety equipment such as gloves and eye protection. Contact RMSTATOR with any questions regarding the use of our flywheel pullers.

Over time, corrosion, over torquing of the fixing bolt or heat cycling can complicate the process of removing the flywheel. Do not use a breaker bar or impact tools to aid in removal of the flywheel. This can damage the flywheel, flywheel puller and the crank causing significant damage to the vehicle.

PRODUCTS / CHARGING SYSTEM

CC	MODEL	FROM	TO	STATOR	REGULATOR RECTIFIER	MOSFET REGULATOR RECTIFIER
KAWASAKI						
260	Ultra 260LX	2007	2010	REPAIR	RM30804	RM30801H
260	Ultra 260X	2009	2010	REPAIR	RM30804	RM30801H
300	Ultra 300LX	2011	2013	REPAIR	RM30804	RM30801H
300	Ultra 300X	2011	2013	REPAIR	RM30804	RM30801H
650	650 SC	1991	1995	REPAIR	RM30905	
650	650 SX	1992	1993	REPAIR	RM30905	
650	650 X2	1992	1995	REPAIR	RM30905	
650	TS Tandem Sport	1989	1996	REPAIR	RM30905	
750	750 SS	1992	1997	REPAIR	RM30Y08	
750	750 ST	1994	1995	REPAIR	RM30Y08	
750	750 STS	1995	1997	REPAIR	RM30Y08	
750	750 STX	1998	1998	REPAIR	RM30Y08	
750	750 Super Sport XI	1993	1997	REPAIR	RM30Y08	
750	750 SX	1992	1995	REPAIR	RM30Y07	
750	750 SXI	1995	1997	REPAIR	RM30Y07	
750	750 SXI Pro	1998	2002	REPAIR	RM30Y07	
750	750 XI Sport	1998	1999	REPAIR	RM30Y08	
750	750 XIR	1994	1994	REPAIR	RM30Y08	
800	800 SX-R	2003	2011	REPAIR	RM30Y07	
1200	1200 STX-R	2002	2005	REPAIR	RM30904	
1200	STX-12F	2003	2003	REPAIR	RM30804	
1200	STX-12F	2004	2007	REPAIR	RM30804	RM30801H
1200	Ultra 150 hp	1999	2005	REPAIR	RM30904	
1500	STX	2009	2010	REPAIR	RM30804	RM30801H
1500	STX-15F	2004	2013	REPAIR	RM30804	RM30801H
1500	Ultra 250X	2007	2008	REPAIR	RM30804	RM30801H
POLARIS						
650	SL 650 STD	1995	1995	REPAIR	RM30908	
700	Freedom	2002	2004	REPAIR	RM30909	
700	Hurricane 700	1996	1997	REPAIR	RM30908	
700	SLH 700	1998	2001	REPAIR	RM30908	
700	Virage	2000	2004	REPAIR	RM30909	
750	SL 750	1994	1995	REPAIR	RM30908	
750	SLTH 700	1998	1999	REPAIR	RM30908	
780	SL 780	1996	1997	REPAIR	RM30908	
780	SLT 780	1996	1997	REPAIR	RM30908	
780	SLX 780	1996	1996	REPAIR	RM30908	
785	Pro 785	2000	2000	REPAIR	RM30908	
800	Octane 800	2002	2004	REPAIR	RM30908	
900	SL 900	1996	1997	REPAIR	RM30908	
1050	SL 1050	1997	1997	REPAIR	RM30908	
1050	SLTX 1050	1996	1999	REPAIR	RM30908	
1050	SLX 1050	2000	2001	REPAIR	RM30908	
1050	SLXH 1050	1998	1998	REPAIR	RM30908	
1100	Genesis	2000	2002	REPAIR	RM30909	
1150	Genesis 1150	1999	1999	REPAIR	RM30908	
1200	Pro 1200	2000	2001	REPAIR	RM30908	
SEA-DOO						
130	GTS	2011	2012	REPAIR		RM30506H
155	GTI	2008	2012	REPAIR		RM30506H
155	GTX	2008	2012	REPAIR		RM30506H
155	RXP	2008	2008	REPAIR		RM30506H
155	WAKE	2008	2012	REPAIR		RM30506H
180	SP	2012	2012	REPAIR		RM30506H
210	Challenger	2010	2012	REPAIR		RM30506H
210	SP	2011	2012	REPAIR		RM30506H
210	WAKE	2010	2012	REPAIR		RM30506H
215	GTR	2012	2012	REPAIR		RM30506H
215	GTX	2008	2012	REPAIR		RM30506H
215	RXP	2004	2007	REPAIR	RM30Y06	
215	RXP	2008	2009	REPAIR		RM30506H
215	WAKE	2008	2012	REPAIR		RM30506H
230	SP	2011	2012	REPAIR		RM30506H
230	WAKE	2009	2012	REPAIR		RM30506H
255	GTX	2009	2009	REPAIR		RM30506H
255	RXP	2008	2011	REPAIR		RM30506H
255	RXT	2008	2009	REPAIR		RM30506H
260	GTX	2010	2012	REPAIR		RM30506H
260	RXP	2012	2012	REPAIR		RM30506H

PRODUCTS / CHARGING SYSTEM

CC	MODEL	FROM	TO	STATOR	REGULATOR RECTIFIER	MOSFET REGULATOR RECTIFIER
260	RXT	2010	2012	REPAIR		RM30506H
580	GT	1990	1991	RM01381 ^b	RM30Y04	
580	GTS	1992	1994	RM01383 ^b	RM30Y04	
580	GTS	1995	1996	REPAIR	RM30Y04	
580	GTX	1992	1994	RM01383 ^b	RM30Y04	
580	GTX	1995	1995	REPAIR	RM30Y04	
580	SP	1989	1989	RM01381 ^b		
580	SP	1990	1991	RM01381 ^b	RM30Y04	
580	SP	1992	1994	RM01383 ^b	RM30Y04	
580	SP	1995	1996	RM01380 ^{mb}	RM30Y04	
580	SPI	1993	1994	RM01383 ^b	RM30Y04	
580	SPI	1995	1996	RM01380 ^{mb}	RM30Y04	
580	SPX	1993	1993	REPAIR	RM30Y04	
580	XP	1991	1991	RM01381 ^b	RM30Y04	
580	XP	1992	1992	REPAIR	RM30Y04	
650	GTX	1995	1995	RM01380 ^{mb}		
650	SPX	1994	1994	REPAIR	RM30Y04	
650	SPX	1995	1995	RM01380 ^{mb}	RM30Y04	
650	SPX	1996	1996	REPAIR	RM30Y04	
650	XP	1992	1992	RM01383 ^b		
650	XP	1993	1994	RM01382 ^b	RM30Y04	
650	XPI	1994	1994	RM01383 ^b	RM30Y04	
720	GS	1997	2001	RM01380 ^{mb}	RM30916	
720	GSI	1997	1997	RM01380 ^{mb}	RM30916	
720	GTI	1996	1996	REPAIR	RM30Y04	
720	GTI	1997	1998	REPAIR	RM30916	
720	GTI	1999	2005	RM01380 ^{mb}	RM30916	
720	GTS	1996	1997	REPAIR	RM30Y04	
720	GTS	1998	2000	RM01380 ^{mb}	RM30Y04	
720	GTS	2001	2001	REPAIR	RM30916	
720	HX	1995	1997	RM01380 ^{mb}	RM30Y04	
720	SP	1997	1997	RM01380 ^{mb}	RM30Y04	
720	SPX	1993	1994	RM01383 ^b	RM30Y04	
720	SPX	1995	1995	REPAIR	RM30Y04	
720	SPX	1996	1996	RM01380 ^{mb}	RM30Y04	
720	XP	1995	1995	RM01380 ^{mb}	RM30Y04	
780	GSX	1999	2000	REPAIR	RM30Y05	
780	GTX	1998	2000	REPAIR	RM30Y05	
780	GTX	2002	2002	REPAIR	RM30Y05	
780	SPX	1997	1997	RM01380 ^{mb}		
782	Challenger	1996	1997	RM01340 ^m	RM30Y02	
800	3D RFI	2005	2005	REPAIR	RM30Y06	
800	GSX	1996	1996	RM01340 ^m	RM30Y02	
800	GSX	1997	1997	RM01340 ^m	RM30917	
800	GSX	1998	1998	RM01340 ^m		
800	GTI	2003	2004	REPAIR	RM30Y05	
800	GTI	2005	2005	REPAIR	RM30Y06	
800	GTX	1996	1997	RM01340 ^m	RM30Y02	
800	SP	1997	1997	REPAIR	RM30Y02	
800	Sportster	1998	1999	REPAIR	RM30916	
800	SPX	1997	1999	RM01340 ^m	RM30Y02	
800	XP	1995	1996	RM01340 ^m	RM30Y02	
800	XP	1997	1997	RM01340 ^m	RM30917	
900	Spark	2014	2015	RM01234		
950	3D DI	2006	2007	REPAIR	RM30Y06	
950	Sportster	2000	2003	RM01340 ^m		
950	Sportster	2004	2006	REPAIR	RM30Y05	
951	GSX	1998	1999	RM01340 ^m		
951	GTX	1998	1999	RM01340 ^m		
951	GTX	2000	2002	RM01340 ^m	RM30Y05	
951	GTX	2003	2003	REPAIR	RM30Y05	
951	LRV	2000	2001	RM01340 ^m		
951	LRV	2002	2003	REPAIR	RM30Y05	
951	RX	2000	2002	RM01340 ^m	RM30Y05	
951	RX	2003	2003	REPAIR	RM30Y05	
951	XP	1998	2002	RM01340 ^m		
951	XP	2003	2004	REPAIR	RM30Y05	
1440	Sportster	2002	2002	REPAIR	RM30916	
1500	Challenger	2000	2001	REPAIR	RM30916	
1500	Challenger	2005	2007	REPAIR	RM30Y06	

Please see the NOTES at the end of this section for additional information.

PRODUCTS / CHARGING SYSTEM

CC	MODEL	FROM	TO	STATOR	REGULATOR RECTIFIER	MOSFET REGULATOR RECTIFIER
1500	Challenger	2008	2012	REPAIR		RM30506H
1500	GTI	2006	2007	REPAIR	RM30Y06	
1500	GTI	2008	2012	REPAIR		RM30506H
1500	GTX	2002	2007	REPAIR	RM30Y06	
1500	RXT	2005	2007	REPAIR	RM30Y06	
1500	RXT	2008	2010	REPAIR		RM30506H
1500	Speedster	2007	2007	REPAIR	RM30Y06	
1500	Speedster	2008	2012	REPAIR		RM30506H
1500	Sportster	2003	2005	REPAIR	RM30Y06	
1564	Speedster	1998	1998	RM01340 ^m	RM30917	
1564	Speedster	1999	1999	RM01340 ^m	RM30916	
3000	Islandia	2006	2007	REPAIR	RM30Y06	
3000	Islandia	2009	2009	REPAIR		RM30506H
3000	Speedster	2004	2007	REPAIR	RM30Y06	
3000	Speedster	2008	2012	REPAIR		RM30506H
3000	Utopia	2006	2007	REPAIR	RM30Y06	
3000	Utopia	2008	2009	REPAIR		RM30506H
4200	Challenger	2007	2007	REPAIR	RM30Y06	
4200	Challenger	2008	2012	REPAIR		RM30506H
YAMAHA						
500	Wave Jammer 500	1989	1990	REPAIR	RM30921	
500	Wave Runner 500	1989	1993	REPAIR	RM30921	
650	Super Jet	1990	1993	RM01371 ^{pb}	RM30922	
650	VXR 650	1991	1993	RM01371 ^{pb}	RM30922	
650	VXR 650	1995	1995	RM01371 ^{pb}	RM30922	
650	Wave Runner 650	1990	1993	RM01371 ^{pb}	RM30922	
650	Wave Runner 650	1995	1995	RM01371 ^{pb}	RM30922	
650	Wave Runner 650	1996	1996	REPAIR	RM30922	
700	FX 1 FX700	1994	1995	RM01371 ^{pb}	RM30922	
700	SJ 700	2001	2002	REPAIR	RM30922	
700	SJ 700	2004	2004	REPAIR	RM30922	
700	Super Jet	1995	1995	RM01371 ^{pb}	RM30922	
700	Super Jet	1996	2000	REPAIR	RM30922	
700	Super Jet	2003	2003	REPAIR	RM30922	
700	Super Jet	2005	2013	REPAIR	RM30922	
700	VXR 700	1993	1994	RM01371 ^{pb}	RM30922	
700	Wave Blaster 700	1993	1995	RM01371 ^{pb}	RM30922	
700	Wave Blaster 700	1996	1996	REPAIR	RM30922	
700	Wave Raider 700	1994	1997	REPAIR	RM30922	
700	Wave Runner 700	1991	1992	REPAIR	RM30922	
700	Wave Runner 700	1994	1995	RM01371 ^{pb}	RM30922	
700	Wave Runner 700	1997	1997	RM01371 ^{pb}	RM30922	
700	Wave Venture 700	1995	1996	REPAIR	RM30922	
700	Wave Venture 700	1998	1998	REPAIR	RM30922	
700	XL 700	1999	2004	REPAIR	RM30922	
760	GP 760	1999	2000	REPAIR	RM30922	
760	Wave Blaster 760	1996	1997	REPAIR	RM30922	
760	Wave Raider 760	1996	1996	REPAIR	RM30922	
760	Wave Runner 760	1997	1998	REPAIR	RM30922	
760	Wave Venture 760	1997	1997	REPAIR	RM30922	
760	XL 760	1998	1999	REPAIR	RM30922	
800	GP 800	1998	2002	REPAIR	RM30Y10	
800	GP 800 R	2003	2005	REPAIR	RM30Y10	
800	XA 800	2004	2004	REPAIR	RM30Y10	
800	XL 800	2000	2000	REPAIR	RM30Y10	
800	XL 800 Z	2001	2001	REPAIR	RM30Y10	
800	XLT 800	2002	2004	REPAIR	RM30Y10	
1000	Waverunner FX 1000	2002	2008	RM01124 ^m	RM30920	
1100	AR 210	2003	2005	REPAIR	RM30Y11	
1100	AR 210	2006	2013	RM01124 ^m	RM30920	
1100	AR 210	2014	2014	RM01124 ^m		
1100	Exciter 135	1998	1998	REPAIR	RM30Y11	
1100	Exciter 270	1998	1999	REPAIR	RM30Y11	
1100	SR 210	2006	2007	RM01124 ^m	RM30920	
1100	SX 210	2006	2006	RM01124 ^m	RM30920	
1100	SX 210	2007	2007	RM01124 ^m		
1100	SX 210	2008	2008	RM01124 ^m	RM30920	
1100	SX 210	2010	2013	RM01124 ^m	RM30920	
1100	SX 210	2014	2014	RM01124 ^m		
1100	Wave Raider 1100	1995	1996	REPAIR	RM30Y10	

PRODUCTS / CHARGING SYSTEM

CC	MODEL	FROM	TO	STATOR	REGULATOR RECTIFIER	MOSFET REGULATOR RECTIFIER
1100	Wave Venture 1100	1996	1997	REPAIR	RM30Y10	
1100	Waverunner FX 1000	2004	2008	RM01124 ^m	RM30920	
1100	Waverunner VX 1100	2005	2013	RM01124 ^m	RM30920	
1100	Waverunner VX 1100	2014	2014	REPAIR	RM30920	
1200	GP 1200	1997	1999	REPAIR	RM30Y11	
1200	GP 1200	2000	2002	REPAIR	RM30923	
1200	SUV 1200	1999	2001	REPAIR	RM30Y11	
1200	SUV 1200	2003	2004	REPAIR	RM30Y11	
1200	SV 1200	2002	2002	REPAIR	RM30Y11	
1200	SV 1200	2004	2004	REPAIR	RM30Y11	
1200	Waverunner XLT 1200	2002	2005	REPAIR	RM30923	
1200	XL 1200	1998	1998	REPAIR	RM30Y11	
1200	XL 1200	1999	2001	REPAIR	RM30923	
1300	GP 1300 R	2003	2008	RM01124 ^m	RM30920	
1800	XR 1800	2000	2001	REPAIR	RM30923	
2000	AR 230	2004	2006	RM01124 ^m	RM30920	
2000	LS 2000	1999	2003	REPAIR	RM30Y11	
2000	SR 230	2003	2005	RM01124 ^m	RM30920	
2000	SR 230	2007	2007	RM01124 ^m	RM30920	
2000	SX 230	2004	2006	RM01124 ^m	RM30920	
2100	212 SS	2008	2010	RM01124 ^m	RM30920	
2100	212 X	2008	2010	RM01124 ^m	RM30920	
2100	232 Limited	2008	2009	RM01124 ^m	RM30920	
2100	AR 230	2005	2007	RM01124 ^m	RM30920	
2100	AR 230	2009	2009	RM01124 ^m	RM30920	
2100	Exciter 220	1996	1998	REPAIR	RM30Y10	
2100	SX 230	2005	2009	RM01124 ^m	RM30920	
2200	LX 2000	2002	2002	REPAIR	RM30Y11	
2200	LX 210	2003	2005	REPAIR	RM30Y11	

NOTES

^m : This part is not plug & play and requires basic mechanical experience to install.

REPAIR : We can repair almost any stator, for more information and repair eligibility, please call **1-877-838-1399** toll free.

P : The stator includes the pick-up coil..

b : The stator includes the backplate.

PRODUCTS / CHARGING SYSTEM



RM01124



RM01234



RM01340



RM01371



RM01380



RM01381



RM01382



RM01383



RM30506H



RM30801H



RM30804



RM30904



RM30905



RM30908



RM30909



RM30916



RM30917



RM30920



RM30921



RM30922



RM30923



RM30Y02



RM30Y04



RM30Y05



RM30Y06



RM30Y07



RM30Y08



RM30Y10



RM30Y11

IGNITION SYSTEM

For OEM cross reference, product specifications and more information please visit: www.rmstator.com

Enhanced Technology

This icon indicates that the product is an advanced technology that either lowers operating temperatures to provide extended longevity or shuts down the system before burning to protect critical electrical components. The Enhanced Technology icon identifies products that offer better performance than the OEM component.

Gaskets

You wouldn't use the same oil filter twice, would you? Then why would you even consider reusing an old gasket? Save yourself the headache and hassle of dealing with a leaking gasket by installing a new gasket every time you open the engine case.

Connectors

Make sure all of your electrical connectors are in proper working order by replacing them along with your new part. Shop connectors at

www.rmstator.com/connectors.

Flywheel Pullers

Make sure you have the right tool for the job. Attempting to remove a flywheel without a flywheel puller can cause significant and costly damage to your crankshaft. Be sure to lubricate the necessary areas liberally and use only the appropriate hand tools. Always wear safety equipment such as gloves and eye protection. Contact RMSTATOR with any questions regarding the use of our flywheel pullers.

Over time, corrosion, over torquing of the fixing bolt or heat cycling can complicate the process of removing the flywheel. Do not use a breaker bar or impact tools to aid in removal of the flywheel. This can damage the flywheel, flywheel puller and the crank causing significant damage to the vehicle.

PRODUCTS / IGNITION SYSTEM

CC	MODEL	FROM	TO	STATOR	PICK-UP COIL	EXTERNAL IGNITION COIL
KAWASAKI						
750	750 SS	1992	1995	REPAIR	RM00102 ^m	
750	750 ST	1994	1995	REPAIR	RM00102 ^m	
750	750 Super Sport XI	1993	1995	REPAIR	RM00102 ^m	
750	750Xi R	1994	1994	REPAIR	RM00102 ^m	
SEA-DOO						
130	GTS	2011	2015	REPAIR		RM06054
155	GTI	2009	2015	REPAIR		RM06054
155	GTX	2009	2015	REPAIR		RM06054
155	WAKE	2009	2015	REPAIR		RM06054
180	SP	2012	2012	REPAIR		RM06054
210	Challenger	2010	2012	REPAIR		RM06054
210	SP	2011	2012	REPAIR		RM06054
210	WAKE	2010	2012	REPAIR		RM06054
215	GTR	2012	2015	REPAIR		RM06054
215	GTX	2009	2015	REPAIR		RM06054
215	RXP	2009	2009	REPAIR		RM06054
215	WAKE	2009	2015	REPAIR		RM06054
230	SP	2011	2012	REPAIR		RM06054
230	WAKE	2009	2012	REPAIR		RM06054
255	GTX	2009	2009	REPAIR		RM06054
255	RXP	2009	2011	REPAIR		RM06054
255	RXT	2009	2009	REPAIR		RM06054
260	GTX	2010	2015	REPAIR		RM06054
260	RXP	2012	2015	REPAIR		RM06054
260	RXT	2010	2013	REPAIR		RM06054
260	RXT	2015	2015	REPAIR		RM06054
580	GT	1990	1991	RM01381 ^b		
580	GTS	1992	1994	RM01383 ^b		
580	GTX	1992	1994	RM01383 ^b		
580	SP	1989	1991	RM01381 ^b		
580	SP	1992	1994	RM01383 ^b		
580	SP	1995	1996	RM01380 ^{mb}		
580	SPI	1993	1994	RM01383 ^b		
580	SPI	1995	1996	RM01380 ^{mb}		
580	XP	1991	1991	RM01381 ^b		
650	GTX	1995	1995	RM01380 ^{mb}		
650	SPX	1995	1995	RM01380 ^{mb}		
650	XP	1992	1992	RM01383 ^b		
650	XP	1993	1994	RM01382 ^b		
650	XPI	1994	1994	RM01383 ^b		
720	GS	1997	2001	RM01380 ^{mb}		
720	GSI	1997	1997	RM01380 ^{mb}		
720	GTI	1999	2005	RM01380 ^{mb}		
720	GTS	1998	2000	RM01380 ^{mb}		
720	HX	1995	1997	RM01380 ^{mb}		
720	SP	1997	1997	RM01380 ^{mb}		
720	SPX	1993	1994	RM01383 ^b		
720	SPX	1996	1996	RM01380 ^{mb}		
720	XP	1995	1995	RM01380 ^{mb}		
780	SPX	1997	1997	RM01380 ^{mb}		
782	Challenger	1996	1997	RM01340 ^m		
800	3D RFI	2005	2005	REPAIR		RM06021
800	GSX	1996	1998	RM01340 ^m		
800	GTI	2003	2005	REPAIR		RM06021
800	GTX	1996	1997	RM01340 ^m		
800	GTX	2000	2002	REPAIR		RM06021
800	SPX	1997	1999	RM01340 ^m		
800	XP	1995	1997	RM01340 ^m		
900	Spark	2014	2015	RM01234		
950	Sportster	2000	2003	RM01340 ^m		
951	GSX	1998	1999	RM01340 ^m		
951	GTX	1998	2002	RM01340 ^m		
951	LRV	2000	2001	RM01340 ^m		
951	RX	2000	2002	RM01340 ^m		
951	XP	1998	2002	RM01340 ^m		
1500	Challenger	2005	2012	REPAIR		RM06054
1500	GTI	2007	2013	REPAIR		RM06054
1500	GTX	2003	2005	REPAIR		RM06054
1500	GTX	2007	2008	REPAIR		RM06054

PRODUCTS / IGNITION SYSTEM

CC	MODEL	FROM	TO	STATOR	PICK-UP COIL	EXTERNAL IGNITION COIL
1500	RXT	2007	2008	REPAIR		RM06054
1500	Speedster	2007	2012	REPAIR		RM06054
1500	Sportster	2003	2006	REPAIR		RM06054
1564	Speedster	1998	1999	RM01340 ^m		
3000	Islandia	2006	2007	REPAIR		RM06054
3000	Islandia	2009	2009	REPAIR		RM06054
3000	Speedster	2004	2012	REPAIR		RM06054
3000	Utopia	2006	2009	REPAIR		RM06054
4200	Challenger	2007	2012	REPAIR		RM06054
YAMAHA						
650	Super Jet	1990	1993	RM01371 ^{pb}		
650	VXR 650	1991	1993	RM01371 ^{pb}		
650	VXR 650	1995	1995	RM01371 ^{pb}		
650	Wave Runner 650	1990	1993	RM01371 ^{pb}		
650	Wave Runner 650	1995	1995	RM01371 ^{pb}		
700	FX 1 FX700	1994	1995	RM01371 ^{pb}		
700	Super Jet	1995	1995	RM01371 ^{pb}		
700	VXR 700	1993	1994	RM01371 ^{pb}		
700	Wave Blaster 700	1993	1995	RM01371 ^{pb}		
700	Wave Runner 700	1994	1995	RM01371 ^{pb}		
700	Wave Runner 700	1997	1997	RM01371 ^{pb}		
1000	Waverunner FX 1000	2002	2004	RM01124 ^m		
1000	Waverunner FX 1000	2005	2008	RM01124 ^m		RM06036-W126
1100	AR 210	2006	2014	RM01124 ^m		
1100	SR 210	2006	2007	RM01124 ^m		
1100	SX 210	2006	2008	RM01124 ^m		
1100	SX 210	2010	2014	RM01124 ^m		
1100	Waverunner FX 1000	2004	2008	RM01124 ^m		RM06036-W126
1100	Waverunner VX 1100	2005	2013	RM01124 ^m		RM06036-W126
1100	Waverunner VX 1100	2014	2014	REPAIR		RM06036-W126
1300	GP 1300 R	2003	2008	RM01124 ^m		
2000	AR 230	2004	2006	RM01124 ^m		
2000	SR 230	2003	2005	RM01124 ^m		
2000	SR 230	2007	2007	RM01124 ^m		
2000	SX 230	2004	2006	RM01124 ^m		
2100	212 SS	2008	2010	RM01124 ^m		
2100	212 X	2008	2010	RM01124 ^m		
2100	232 Limited	2008	2009	RM01124 ^m		
2100	AR 230	2005	2007	RM01124 ^m		
2100	AR 230	2009	2009	RM01124 ^m		
2100	SX 230	2005	2009	RM01124 ^m		

NOTES

m : This part is not plug & play and requires basic mechanical experience to install.

REPAIR : We can repair almost any stator, for more information and repair eligibility, please call **1-877-838-1399** toll free.

P : The stator includes the pick-up coil.

b : The stator includes the backplate.

PRODUCTS / IGNITION SYSTEM



RM00102



RM01124



RM01234



RM01340



RM01371



RM01380



RM01381



RM01382




RM01383



RM06021



RM06036-W126



RM06054

STARTING SYSTEM

For OEM cross reference, product specifications and more information please visit: www.rmstator.com

Enhanced Technology

This icon indicates that the product is an advanced technology that either lowers operating temperatures to provide extended longevity or shuts down the system before burning to protect critical electrical components. The Enhanced Technology icon identifies products that offer better performance than the OEM component.

Gaskets

You wouldn't use the same oil filter twice, would you? Then why would you even consider reusing an old gasket? Save yourself the headache and hassle of dealing with a leaking gasket by installing a new gasket every time you open the engine case.

Connectors

Make sure all of your electrical connectors are in proper working order by replacing them along with your new part. Shop connectors at www.rmstator.com/connectors.

Flywheel Pullers

Make sure you have the right tool for the job. Attempting to remove a flywheel without a flywheel puller can cause significant and costly damage to your crankshaft. Be sure to lubricate the necessary areas liberally and use only the appropriate hand tools. Always wear safety equipment such as gloves and eye protection. Contact RMSTATOR with any questions regarding the use of our flywheel pullers.

Over time, corrosion, over torquing of the fixing bolt or heat cycling can complicate the process of removing the flywheel. Do not use a breaker bar or impact tools to aid in removal of the flywheel. This can damage the flywheel, flywheel puller and the crank causing significant damage to the vehicle.

PRODUCTS / STARTING SYSTEM

CC	MODEL	FROM	TO	STARTER DRIVE
KAWASAKI				
120	Jet Mate	1989	1992	RM16000
650	650 SC	1991	1995	RM16000
650	650 SX	1987	1993	RM16000
650	650 X2	1986	1987	RM16000
650	650 X2	1989	1995	RM16000
650	TS Tandem Sport	1989	1995	RM16000
750	750 SS	1992	1995	RM16000
750	750 SX	1993	1995	RM16000
750	750 SXI	1995	1997	RM16000
750	750 XI Sport	1998	1999	RM16000
750	750 XIR	1994	1994	RM16000
750	750 ZXi	1995	1997	RM16000
750	ST	1994	1995	RM16000
750	STS	1995	1996	RM16000
750	Super Sport XI	1993	1997	RM16000
750	SXI PRO	1998	2002	RM16000
800	800 SX-R	2003	2011	RM16000
900	900 STS	2001	2002	RM16000
900	900 STX	1997	2006	RM16000
900	900 ZXi	1995	1997	RM16000
1070	Ultra 130	2002	2004	RM16000
1100	1100 STX	1997	2003	RM16000
1100	1100 Zxi	1996	2003	RM16000
POLARIS				
650	SL 650	1992	1995	RM16003
650	SL 650 STD	1995	1995	RM16003
700	Freedom	2002	2004	RM16003
700	Hurricane	1996	1997	RM16003
700	SL	1997	1997	RM16003
700	SL 700	1996	1997	RM16003
700	SL 780	1996	1997	RM16003
700	SL 900	1996	1997	RM16003
700	SLH 700	1998	2001	RM16003
700	Virage	2000	2004	RM16003
750	SL 750	1993	1995	RM16003
750	SLT 700	1996	1997	RM16003
750	SLT 750	1994	1995	RM16003
750	SLT 780	1996	1997	RM16003
750	SLTH 700	1998	1999	RM16003
785	Pro 785	1999	2000	RM16003
800	Octane 800	2002	2004	RM16003
1050	SLTX 1050	1996	1999	RM16003
1050	SLX 1050	1999	1999	RM16003
1050	SLX 1150	2000	2001	RM16003
1050	SLX 780	1995	1996	RM16003
1050	SLX 785 PRO	1997	1998	RM16003
1050	SLXH 1050	1998	1998	RM16003
1100	Genesis	1999	2004	RM16003
1200	MSX	2004	2004	RM16003
1200	Pro 1200	2000	2001	RM16003
YAMAHA				
650	Super Jet	1990	1993	RM16006
650	VXR 650	1991	1992	RM16006
650	VXR 650	1995	1995	RM16006
650	Wave Runner 650	1990	1993	RM16006
650	Wave Runner 650	1995	1996	RM16006
700	FX 1 FX700	1994	1995	RM16006
700	SJ 700	2001	2004	RM16006
700	Super Jet	1995	2000	RM16006
700	Super Jet	2003	2013	RM16006
700	VXR 700	1993	1994	RM16006
700	Wave Blaster 700	1993	1996	RM16006
700	Wave Raider 700	1994	1997	RM16006
700	Wave Runner 700	1994	1997	RM16006
700	Wave Venture 700	1996	1996	RM16006
700	Wave Venture 700	1998	1998	RM16006
700	XL 700	1999	2004	RM16006
700	XLT 700	2003	2003	RM16006
760	GP 760	1999	2000	RM16006
760	Wave Blaster 760	1996	1997	RM16006

PRODUCTS / STARTING SYSTEM

CC	MODEL	FROM	TO	STARTER DRIVE
760	Wave Raider 760	1996	1996	RM16006
760	Wave Runner 760	1998	1998	RM16006
760	Wave Venture 760	1997	1997	RM16006
760	XL 760	1998	1999	RM16006
800	GP 800	1998	1998	RM16006
800	GP 800	2000	2002	RM16006
800	GP 800	2005	2005	RM16006
800	GP 800 R	2003	2004	RM16006
800	XA 800	2004	2004	RM16006
800	XL 800	2000	2000	RM16006
800	XL 800 Z	2001	2001	RM16006
800	XLT 800	2002	2003	RM16006
1100	AR 210	2003	2005	RM16007
1100	Exciter 135	1999	1999	RM16007
1100	Exciter 270	1999	1999	RM16007
1100	Wave Raider 1100	1995	1996	RM16006
1100	Wave Venture 1100	1996	1997	RM16006
1200	GP 1200	1997	2002	RM16006
1200	SUV 1200	1999	2001	RM16006
1200	SUV 1200	2003	2003	RM16006
1200	SV 1200	2002	2002	RM16006
1200	SV 1200	2004	2004	RM16006
1200	XA 1200	2004	2004	RM16006
1200	XL 1200	1998	2001	RM16006
1200	XLT 1200	2002	2003	RM16006
1200	XLT 1200	2005	2005	RM16006
1300	GP 1300 R	2003	2008	RM16006
1800	XR 1800	2000	2001	RM16007
2000	LS 2000	1999	2003	RM16007
2100	Exciter 220	1996	1998	RM16007
2200	LX 2000	2002	2002	RM16007
2200	LX 210	2003	2005	RM16007



RM16000



RM16003



RM16006



RM16007

For OEM reverse lookup, specs and more please visit www.rmstator.com

Can't find the part you're looking for? Call us 1-877-838-1399 or contact us by email at support@rmstator.com

STARTING SYSTEM

TOOLS AND MISC. PRODUCTS

For OEM cross reference, product specifications and more information please visit:

www.rmstator.com



Enhanced Technology

This icon indicates that the product is an advanced technology that either lowers operating temperatures to provide extended longevity or shuts down the system before burning to protect critical electrical components. The Enhanced Technology icon identifies products that offer better performance than the OEM component.

Gaskets

You wouldn't use the same oil filter twice, would you? Then why would you even consider reusing an old gasket? Save yourself the headache and hassle of dealing with a leaking gasket by installing a new gasket every time you open the engine case.

Connectors

Make sure all of your electrical connectors are in proper working order by replacing them along with your new part. Shop connectors at

www.rmstator.com/connectors.

Flywheel Pullers

Make sure you have the right tool for the job. Attempting to remove a flywheel without a flywheel puller can cause significant and costly damage to your crankshaft. Be sure to lubricate the necessary areas liberally and use only the appropriate hand tools. Always wear safety equipment such as gloves and eye protection. Contact RMSTATOR with any questions regarding the use of our flywheel pullers.

Over time, corrosion, over torquing of the fixing bolt or heat cycling can complicate the process of removing the flywheel. Do not use a breaker bar or impact tools to aid in removal of the flywheel. This can damage the flywheel, flywheel puller and the crank causing significant damage to the vehicle.

TOOLS AND MISC. PRODUCTS

/ SPARK PLUG CAPS

CONFIGURATION	RMSTATOR PART NO	NGK PART NO	NGK STOCK NO	RESISTANCE
	RM07100	LB01EP LB05EP	8328 8020	1K OHM 5K OHM
	RM07102	N.D.	N.D.	N.D.
	RM07103	TB05EMA	8636	5K OHM
	RM07104	VB05FP VD05FP	8413 8429	5K OHM
	RM07107	N.D.	N.D.	N.D.



RM03800 / Heavy Duty AC Voltage Regulator Rectifier

- 12 Volt regulator used by multiple Baja winners
- Heavy duty and improved regulator rectifier
- For use with all standard halogen and quartz lights
- Precise voltage control, eliminates light burnout
- Reduces flickering and dimming
- Easy installation
- Works with all other OEM components
- Rated at 225 watts
- All products are tested before they are shipped
- One year limited warranty



RM03900 / Universal Voltage Regulator Rectifier Honda

- Direct replacement of your OEM unit
- Plug-and-play, direct fit, easy installation
- No assembly required
- Premium quality electronic components
- Improved heat sink and charging capabilities
- Overall quality is far superior to the OEM equipment
- All products are tested before they are shipped
- One year limited warranty



RM09021 / Winch Starter Relay Solenoid Switch Universal

- Universal Part for ATVs
- Works with all winches up to 4500 lbs
- Mounting equipment included
- All products are tested before they are shipped
- One year limited warranty

TOOLS AND MISC. PRODUCTS / UNIVERSAL PRODUCTS



RM11303 / Universal Flywheel Puller

Indispensable tool for removing magneto flywheels without causing damage to the crankshaft threads

- This truly universal tool works on ATVs, snowmobiles, PWCs, motorcycles, lawn mowers and chainsaws*
- Constructed of solid steel with a silver oxide finish to prevent corrosion
- One year limited warranty

*Works with most flywheels having three threaded holes for pullers around the center flywheel nut hole. A must-have tool for any mechanic.



RM30510H / Improved Universal Mosfet Voltage Regulator

Outfit any vehicle with a single phase or three phase charging system. It runs cooler than all OEM diode style regulators. In addition, this rectifier provides overheat protection; if it becomes too hot it will automatically turn off and cool down.

- Direct OEM replacement
- Plug-and-play, direct fit, easy installation.
- Used to upgrade most 2 wire and 3 wire stator systems
- Improved heat sink and charging capabilities
- Premium quality electronic components.
- Overall quality is far superior to the OEM equipment
- All products are tested before they are shipped
- One year limited warranty



RM30511H / Improved Universal Mosfet Voltage Regulator

The Universal Mosfet Voltage Regulator runs cooler than all OEM diode style regulators and features overheat protection; if it becomes too hot it will automatically turn off and cool down.

- Can handle up to 350 watts
- Distance between fixation holes: 103 mm
- Number of wires: 7
- Must reinstall your original connector
- Once your connector is reinstalled, our part becomes a plug-and-play unit, direct fit, and easy to install
- Overall quality is far superior to the OEM equipment
- Improved heat sink and charging capabilities
- Premium quality electronic components
- All products shipped are tested before they are shipped
- One year limited warranty






RM30512H / Universal Mosfet Regulator rectifier

The Universal Mosfet Regulator Rectifier runs cooler than all OEM diode style regulators and features overheat protection; if it becomes too hot it will automatically turn off and cool down.

- Handles up to 350 watts
- Distance between fixation holes: 95 mm
- Number of wires: 7
- Must reinstall your original connector
- Once your connector is reinstalled, our part becomes a plug-and-play unit, direct fit, and easy to install
- Overall quality exceeds that of the OEM equipment
- Improved heat sink and charging capabilities
- Premium quality electronic components
- All products are tested before they are shipped
- One year limited warranty



RM30513H / Universal Mosfet Regulator Rectifier

The Universal Mosfet Regulator Rectifier runs cooler than all OEM diode style regulators and features overheat protection; if it becomes too hot it will automatically turn off and cool down.

CONTACT US

Toll Free (Canada & USA): 1-877-838-1399

Local & International: 819-849-7333

Fax: 819-849-6660

For written inquiries, FAQ and more, visit our Online Customer Service Center at support.rmstator.com or contact us by e-mail at support@rmstator.com

Business hours

Eastern Standard Time

Monday to Thursday: 8AM to 5PM

Friday: 8AM to 4PM

Saturday & Sunday: Closed

Headquarters

Canadian Headquarters

541, Main Ouest, Coaticook
(Québec) Canada J1A 1R2

RMSTATOR Return Addresses

Canadian &

International Customers

RMSTATOR

541, Main Ouest, Coaticook

(Quebec) Canada, J1A 1R2

United States Customers

RMSTATOR

395 Caswell Ave

Derby line VT 05830

Order fulfillment

Orders received after 11:30am EST will only be sent out the next business day.

Sales

Any sales inquiries, new corporate accounts and opportunities requests must be sent to

sales@rmstator.com

RMSTATOR clients around the world



RMSTATOR

Toll Free : 1-877-838-1399

www.rmstator.com



GUILLAUME



JEAN-MICHEL



LUCIE



ROGER



SHARON



SUSAN



LÉANNE



LAURENT



PHOEBE



SYLVAIN



SEAN



LIONEL



MICHEL



SHEILA



THE POWER
IN POWERSPORT
— SINCE 1993 —



EDIN



JESSICA



MÉLANIE



SÉBASTIEN



VÉRONIQUE



PHÉBÉE



KIMBERLY



SIMON



CÉDRIC



CHELSEA